

Cleanup Site Details

Cleanup Site ID: 3070

Cleanup Site ID: 3070
Facility/Site ID: 2401
UST ID: N/A
[Site Page](#)
[Site Documents](#)
[View Map](#)
Cleanup Site Name: Olympic Pipe Line Co Kent
[Glossary](#)
Alternate Names: OLYMPIC PIPE LINE CO KENT, OPLC Kent Block Valve

LOCATION

Address: 74TH AVE S & S 259TH ST
City: KENT
Zip Code: 98032
County: King
Latitude: 47.37038
Longitude: -122.24066
WRIA: 9
Legislative District: 33
Congressional District: 9
TRS: 22N 4E 25

DETAIL

Status: No Further Action
NFA Received? Yes
Is PSI site? No
Statute: MTCA
NFA Date: 1/17/2017
Current VCP? No
Past VCP? Yes
Site Rank: 2 - Moderate-High Risk
NFA Reason: Voluntary Cleanup Program Review
Brownfield? No
Site Manager: Myers, Dale R
Responsible Unit: Northwest
Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
OLYMPIC PIPE LINE CO KENT	Upland	No Further Action Required	NW	Myers, Dale R	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Non-Halogenated Solvents	RB	RB			B	
Other Non-Halogenated Organics	RB	RB				
Petroleum Products-Unspecified	RB	RB			B	
Petroleum-Diesel		RB				
Petroleum-Gasoline	RB	RB				

Key:
B - Below Cleanup Level
C - Confirmed Above Cleanup Level
RA - Remediated-Above
S - Suspected
R - Remediated
RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		2/19/1992
Site Hazard Assessment/Federal Site Inspection	Completed	8/13/1999	1/24/2000
Hazardous Sites Listing/NPL	Completed		2/29/2000
Non-LUST Ind Report Received	Completed		2/23/2011
Non-LUST Ind Report Received	Completed		12/28/2011
VCP Receipt of Plan or Report	Completed		1/14/2013

Cleanup Site Details

Cleanup Site ID: 3070

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Opinion on Remedial Investigation	Completed	4/2/2013	6/12/2013
Non-LUST Ind Report Received	Completed		8/19/2013
VCP Receipt of Plan or Report	Completed		3/31/2014
VCP Receipt of Plan or Report	Completed		8/26/2014
VCP Opinion on Remedial Investigation Work Plan	Canceled	10/30/2014	
VCP Receipt of Plan or Report	Completed		11/25/2015
VCP Opinion on Feasibility Study	Canceled	11/25/2015	
VCP Opinion on Site Cleanup	Completed	11/25/2015	1/17/2017
VCP Receipt of Plan or Report	Completed		3/31/2016
Remove site from Hazardous Sites List	Completed		1/17/2017
Site Status Changed to NFA	Completed		1/17/2017
VCP Receipt of Plan or Report	Completed		6/2/2017