

Cleanup Site Details

Cleanup Site ID: 3072

Cleanup Site ID: 3072 Facility/Site ID: 1193 UST ID: 12542 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Mason County Fire District 5 Station 5 [Glossary](#)

Alternate Names: MASON COUNTY FIRE DISTRICT 5 STATION 5, MASON COUNTY FIRE DISTRICT STATION 5, STATION 5

LOCATION

Address: E 6011 AGATE RD City: SHELTON Zip Code: 98584 County: Mason
Latitude: 47.21441 Longitude: -122.96595 WRIA: 14 Legislative District: 35 Congressional District: 6 TRS: 20N 2W 17

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Southwest Region Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
MASON COUNTY FIRE DISTRICT STATION 5	Upland	Cleanup Started	SW	Southwest Region	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics	C	C				
Petroleum-Other	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		3/1/1995
LUST - Site Characterization Report	Completed		5/25/1995
Site Discovery/Release Report Received	Completed		7/20/1995
Order/Decree/Amendment	In Process	10/2/1995	
LUST - Report Received	Completed		10/15/1995
Remedial Investigation and/or Feasibility Study	Completed	3/15/1996	6/1/1996
Order/Decree/Amendment	In Process	6/12/1996	
Remedial Investigation and/or Feasibility Study	Completed	7/12/1996	6/12/1998

Cleanup Site Details

Cleanup Site ID: 3072

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Cleanup Action Plan	Canceled	7/12/1997	9/1/2001
O & M	In Process	8/1/1997	
LUST - Report Received	Completed		8/11/1997
LUST - Report Received	Completed		12/11/1998
LUST - Site Characterization Report	Completed		5/16/2002
LUST - Report Received	Completed		8/26/2002
LUST - Report Received	Completed		6/13/2003
LUST - Report Received	Completed		6/13/2003
LUST - Report Received	Completed		6/13/2003
LUST - Report Received	Completed		8/27/2003
LUST - Site Characterization Report	Completed		12/1/2005
LUST - Report Received	Completed		10/10/2007
LUST - Report Received	Completed		6/4/2008
LUST - Report Received	Completed		12/12/2008
LUST - Report Received	Completed		7/21/2009
LUST - Report Received	Completed		12/7/2009
Remedial Investigation and/or Feasibility Study	In Process	12/3/2013	