

Cleanup Site Details

Cleanup Site ID: 308

Cleanup Site ID: 308	Facility/Site ID: 513712	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: WA DOT I5 MP 197 Marysville					Glossary
Alternate Names: WA DOT I5 MP 197 MARYSVILLE					

LOCATION

Address: I5 AT MP 197 SB			City: MARYSVILLE	Zip Code: 98270	County: Snohomish
Latitude: 48.02789	Longitude: -122.17682	WRIA: 7	Legislative District: 38	Congressional District: 2	TRS: 29N 5E 4

DETAIL

Status: Awaiting Cleanup	NFA Received? No	Is PSI site? Yes
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: 4 - Low-Moderate Risk	NFA Reason: N/A	Brownfield? No
Site Manager: Northwest Region	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
WA DOT I5 MP 197 Marysville	Upland	Awaiting Cleanup	NW	Northwest Region	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified	C	S	S		S	

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		8/24/2007
Initial Investigation / Federal Preliminary Assessment	Completed		11/7/2007
Early Notice Letter(s)	Completed		1/23/2008
Site Hazard Assessment/Federal Site Inspection	Completed	5/13/2008	7/17/2008
Hazardous Sites Listing/NPL	Completed		7/17/2008