

Cleanup Site Details

Cleanup Site ID: 3248

Cleanup Site ID: 3248 **Facility/Site ID:** 459 **UST ID:** 102323 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: CMX Corp [Glossary](#)
Alternate Names: CMX Corp, CMX CORPORATION

LOCATION

Address: 206 W MEAD AVE **City:** YAKIMA **Zip Code:** 98902 **County:** Yakima
Latitude: 46.57786 **Longitude:** -120.50856 **WRIA:** 37 **Legislative District:** 14 **Congressional District:** 4 **TRS:** 13N 19E 31

DETAIL

Status: Cleanup Complete-Active O&M/Monitoring **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 3 - Moderate Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Parker, Kyle **Responsible Unit:** Central **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CMX Corp	Upland	Cleanup Complete-Active O&M/Monitoring ongoing	CE	Parker, Kyle	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	S	S				
Halogenated Organics	RB	S				
Metals Priority Pollutants	S	S				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		4/2/1985
Initial Investigation / Federal Preliminary Assessment	Completed		8/15/1988
Site Hazard Assessment/Federal Site Inspection	Completed	2/13/1989	3/27/1989
Site Hazard Assessment/Federal Site Inspection	Completed	1/1/1990	2/9/1990
Site Hazard Assessment/Federal Site Inspection	Completed	1/15/1991	6/30/1991
Hazardous Sites Listing/NPL	Completed		8/27/1991
Order/Decree/Amendment	Completed	2/11/1992	1/1/1900

Cleanup Site Details

Cleanup Site ID: 3248

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Interim Action	Completed	3/19/1992	3/27/1992
Order/Decree/Amendment	Completed	8/28/1992	1/1/1900
Order/Decree/Amendment	Completed	1/28/1993	1/1/1900
Order/Decree/Amendment	In Process	10/20/1993	