

Cleanup Site Details

Cleanup Site ID: 3342

Cleanup Site ID: 3342 Facility/Site ID: 8465344 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: R J Mine Glossary

Alternate Names: R J Mine

LOCATION

Address: City: Colville Zip Code: 99114 County: Stevens

Latitude: 48.73181 Longitude: -117.87660 WRIA: 61 Legislative District: 7 Congressional District: 5 TRS: 37N 39E 3

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Eastern Region Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name Unit Type Unit Status Resp Unit Unit Manager Current Process

R J Mine Upland Awaiting Cleanup EA Eastern Region No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

 MEDIA

 Contaminant
 Soil
 Groundwater
 Surface Water
 Sediment
 Air
 Bedrock

 Metals Priority Pollutants
 C
 C
 Image: Contaminant of the priority Pollutants of the priority Polluta

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity Status Start Date End Date/Completion Date

Initial Investigation / Federal Preliminary Assessment Completed 6/20/2001

Toxics Cleanup Program Report Generated: 6/2/2025 Page 1 of 1