

# Cleanup Site Details

Cleanup Site ID: 34

Cleanup Site ID: 34      Facility/Site ID: 2104      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: BNSF Railway Skykomish      [Glossary](#)

**Alternate Names:** BNR MAINT & FUELING FACILITY, BNSF FORMER MAINTANENCE & FUELING FACILITY SKYKOMISH, BNSF Railway Skykomish, BNSF RAILWAY SKYKOMISH FACILITY, Burlington Northern & Santa Fe RR, Burlington Northern Rail Yard

## LOCATION

**Address:** SE OF INT OF 5TH ST N & RAILROAD AVE      **City:** SKYKOMISH      **Zip Code:** 98288      **County:** King  
**Latitude:** 47.70896      **Longitude:** -121.36206      **WRIA:** 7      **Legislative District:** 39      **Congressional District:** 1      **TRS:** 26N 11E 26

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** No  
**Site Rank:** 1 - Highest Assessed Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Bushnell, Tanner      **Responsible Unit:** Northwest      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
BNSF Railway Skykomish	Sediment	Cleanup Started	HQ	Adolphson, Pete	Ecology-supervised or conducted
BNSF Railway Skykomish	Upland	Cleanup Started	NW	Bushnell, Tanner	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic		C				
Metals Priority Pollutants	C	C				
Petroleum Products-Unspecified	C	C	C	C		
Polychlorinated biPhenyls (PCB)	C	C				
Polycyclic Aromatic Hydrocarbons	C	C		C		

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
Site Hazard Assessment	Completed	2/1/1991	6/30/1991
Hazardous Sites Listing	Completed		8/30/1991
Remedial Investigation and/or Feasibility Study	Completed	9/16/1993	8/11/2005
Interim Action	Completed	2/1/2001	12/30/2002

# Cleanup Site Details

Cleanup Site ID: 34

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Cleanup Action Plan	Completed	8/16/2005	10/30/2007
Interim Action	Completed	1/1/2006	10/30/2009
Order/Decree/Amendment	In Process	5/19/2006	
Order/Decree/Amendment	In Process	5/19/2006	
Cleanup - Construction	In Process	10/1/2007	
Non-LUST Ind Report Received	Completed		6/2/2021
Non-LUST Ind Report Received	Completed		6/2/2021
SHARP Assessment	Completed		8/28/2025