

Cleanup Site Details

Cleanup Site ID: 34

Cleanup Site ID: 34 Facility/Site ID: 2104 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: BNSF Railway Skykomish [Glossary](#)

Alternate Names: BNR MAINT & FUELING FACILITY, BNSF FORMER MAINTANENCE & FUELING FACILITY SKYKOMISH, BNSF Railway Skykomish, BNSF RAILWAY SKYKOMISH FACILITY, Burlington Northern & Santa Fe RR, Burlington Northern Rail Yard

LOCATION

Address: SE OF INT OF 5TH ST N & RAILROAD AVE **City:** SKYKOMISH **Zip Code:** 98288 **County:** King
Latitude: 47.70896 **Longitude:** -121.36206 **WRIA:** 7 **Legislative District:** 39 **Congressional District:** 1 **TRS:** 26N 11E 26

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Bushnell, Tanner **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|------------------------|-----------|-----------------|-----------|------------------|---------------------------------|
| BNSF Railway Skykomish | Sediment | Cleanup Started | HQ | Adolphson, Pete | Ecology-supervised or conducted |
| BNSF Railway Skykomish | Upland | Cleanup Started | NW | Bushnell, Tanner | Ecology-supervised or conducted |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

| MEDIA | | | | | | |
|----------------------------------|------|-------------|---------------|----------|-----|---------|
| Contaminant | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Arsenic | | C | | | | |
| Metals Priority Pollutants | C | C | | | | |
| Petroleum Products-Unspecified | C | C | C | C | | |
| Polychlorinated biPhenyls (PCB) | C | C | | | | |
| Polycyclic Aromatic Hydrocarbons | C | C | | C | | |

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|---|-----------|------------|---------------------------|
| Site Discovery/Release Report Received | Completed | | 3/1/1988 |
| Site Hazard Assessment | Completed | 2/1/1991 | 6/30/1991 |
| Hazardous Sites Listing | Completed | | 8/30/1991 |
| Remedial Investigation and/or Feasibility Study | Completed | 9/16/1993 | 8/11/2005 |
| Interim Action | Completed | 2/1/2001 | 12/30/2002 |

Cleanup Site Details

Cleanup Site ID: 34

| SITE ACTIVITIES | | | |
|------------------------------|------------|------------|------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| Cleanup Action Plan | Completed | 8/16/2005 | 10/30/2007 |
| Interim Action | Completed | 1/1/2006 | 10/30/2009 |
| Order/Decree/Amendment | In Process | 5/19/2006 | |
| Order/Decree/Amendment | In Process | 5/19/2006 | |
| Cleanup - Construction | In Process | 10/1/2007 | |
| Non-LUST Ind Report Received | Completed | | 6/2/2021 |
| Non-LUST Ind Report Received | Completed | | 6/2/2021 |