

Cleanup Site Details

Cleanup Site ID: 34

Cleanup Site ID: 34 Facility/Site ID: 2104 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: BNSF Railway Skykomish [Glossary](#)

Alternate Names: BNR MAINT & FUELING FACILITY, BNSF FORMER MAINTANENCE & FUELING FACILITY SKYKOMISH, BNSF Railway Skykomish, BNSF RAILWAY SKYKOMISH FACILITY, Burlington Northern & Santa Fe RR, Burlington Northern Rail Yard

LOCATION

Address: SE OF INT OF 5TH ST N & RAILROAD AVE **City:** SKYKOMISH **Zip Code:** 98288 **County:** King
Latitude: 47.70896 **Longitude:** -121.36206 **WRIA:** 7 **Legislative District:** 39 **Congressional District:** 1 **TRS:** 26N 11E 26

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Bushnell, Tanner **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
BNSF Railway Skykomish	Sediment	Cleanup Started	HQ	Adolphson, Pete	Ecology-supervised or conducted
BNSF Railway Skykomish	Upland	Cleanup Started	NW	Bushnell, Tanner	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic		C				
Metals Priority Pollutants	C	C				
Petroleum Products-Unspecified	C	C	C	C		
Polychlorinated biPhenyls (PCB)	C	C				
Polycyclic Aromatic Hydrocarbons	C	C		C		

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Site Hazard Assessment/Federal Site Inspection	Completed	2/1/1991	6/30/1991
Hazardous Sites Listing/NPL	Completed		8/30/1991
Remedial Investigation and/or Feasibility Study	Completed	9/16/1993	8/11/2005
Interim Action	Completed	2/1/2001	12/30/2002

Cleanup Site Details

Cleanup Site ID: 34

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Cleanup Action Plan	Completed	8/16/2005	10/30/2007
Interim Action	Completed	1/1/2006	10/30/2009
Cleanup - Construction	In Process	10/1/2007	
Non-LUST Ind Report Received	Completed		6/2/2021
Non-LUST Ind Report Received	Completed		6/2/2021