

Cleanup Site Details

Cleanup Site ID: 3418
Cleanup Site ID: 3418 **Facility/Site ID:** 2864 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Central Waterfront [Glossary](#)
Alternate Names: CENTRAL WATERFRONT, Old City Dump, ROEDER AVE LANDFILL

LOCATION
Address: F ST **City:** BELLINGHAM **Zip Code:** 98225 **County:** Whatcom
Latitude: 48.75545 **Longitude:** -122.48999 **WRIA:** 1 **Legislative District:** 42 **Congressional District:** 2 **TRS:** 38N 2E 25

DETAIL

Status: Cleanup Started	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? Yes
Site Rank: 2 - Moderate-High Risk	NFA Reason: N/A	Brownfield? No
Site Manager: Rapp, John	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Roeder Ave Landfill	Upland	Cleanup Started	NW	Rapp, John	Ecology-supervised or conducted
Chevron Bellingham Terminal 100-1350	Upland	Cleanup Started	NW	Rapp, John	Ecology-supervised or conducted
Olivine Corp Hilton Ave Uplands	Upland	Cleanup Started	NW	Rapp, John	Ecology-supervised or conducted
Colony Wharf (BCI)	Upland	Cleanup Started	NW	Rapp, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic		C				
Base/Neutral/Acid Organics	S	S	S			
Benzene	C	C				
Conventional Contaminants, Organic	C					
Halogenated Organics	S	S	S			
Lead	C	C				
Mercury		C				
Metals - Other		C				
Metals Priority Pollutants	C	C				
Non-Halogenated Solvents	C	C	C		S	
Other Halogenated Organics					S	
Other Non-Halogenated Organics		C				

Cleanup Site Details

Cleanup Site ID: 3418

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified	S	S	S			
Petroleum-Diesel	C	C				
Petroleum-Gasoline	C	C				
Petroleum-Other	C	C	C		S	
Phenolic Compounds	S	S	S		S	
Polycyclic Aromatic Hydrocarbons	C				S	

Key:

B - Below Cleanup Level
S - Suspected

C - Confirmed Above Cleanup Level
R - Remediated

RA - Remediated-Above
RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Site Hazard Assessment/Federal Site Inspection	Completed	3/21/1995	6/29/1995
Hazardous Sites Listing/NPL	Completed		8/22/1995
VCP Opinion on Remedial Investigation Work Plan	Canceled	4/21/1998	1/1/1900
VCP Opinion on Remedial Investigation Work Plan	Completed	6/26/1998	10/15/1999
Remedial Investigation and/or Feasibility Study	Completed	5/1/2002	4/30/2009
Remedial Investigation and/or Feasibility Study	Completed	5/1/2002	3/30/2018
Interim Action - Plan	Completed	7/31/2012	9/30/2012
Interim Action - Construction	Completed	9/30/2012	5/31/2016
Cleanup Action Plan	In Process	11/13/2018	
Site Hazard Assessment/Federal Site Inspection	Completed		2/9/2024