

Cleanup Site Details

Cleanup Site ID: 3444 Facility/Site ID: 93937775 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 3444

Cleanup Site Name: Port Gamble Bay and Mill Site

Alternate Names: DNR AQUATIC LAND LEASE AREA FORMER, Pope & Talbot Inc Sawmill, POPE & TALBOT PORT GAMBLE MILL, Port

Gamble Bay & Mill Site, Port Gamble Bay and Mill Site, Port Gamble Log Storage Lease Area

LOCATION

Address: VIEW DRIVE City: PORT GAMBLE Zip Code: 98364 County: Kitsap

Latitude: 47.85438 Longitude: -122.58255 WRIA: 15 Legislative District: 23 Congressional District: 6 TRS: 27N 2E 5

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No

Site Manager: King, Corey Responsible Unit: Headquarters Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Port Gamble Log Storage Lease Area	Sediment	Awaiting Cleanup	HQ	King, Corey	Ecology-supervised or conducted
Pope & Talbot Inc Sawmill	Sediment	Construction Complete- Performance Monitoring	HQ	King, Corey	Ecology-supervised or conducted
Pope & Talbot Inc Sawmill	Upland	Cleanup Started	HQ	King, Corey	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Arsenic	С	С					
Base/Neutral/Acid Organics		S					
Bioassay Benthic Failures				С			
Halogenated Organics	С	S	S	С	S		
Metals - Other	S	S		С			
Metals Priority Pollutants	С	С	S	С	S		
Other Deleterious Substances			С	С			
Petroleum Products-Unspecified	С	С			S		
Phenolic Compounds				С			
Polychlorinated biPhenyls (PCB)	С	S	S				
Polycyclic Aromatic Hydrocarbons	С	S	S	С	S		

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

Toxics Cleanup Program Report Generated: 10/30/2025 Page 1 of 2



Cleanup Site Details

Cleanup :	Site ID:	3444
-----------	----------	------

SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
Order/Decree/Amendment	In Process				
Order/Decree/Amendment	In Process				
Site Discovery/Release Report Received	Completed		10/17/1996		
Initial Investigation / Federal Preliminary Assessment	Completed		4/3/2000		
Initial Investigation / Federal Preliminary Assessment	Completed		3/20/2001		
Early Notice Letter(s)	Completed		4/11/2001		
Site Hazard Assessment	Completed	4/18/2001	8/21/2001		
Hazardous Sites Listing	Completed		8/28/2001		
VCP Opinion on Cleanup Action	Canceled	3/20/2002	1/1/1900		
Site Characterization	Completed	4/9/2003	7/9/2003		
VCP Opinion on Site Cleanup	Completed	4/9/2003	7/21/2003		
Remedial Investigation and/or Feasibility Study	Completed	2/1/2007	2/1/2010		
Initial Investigation / Federal Preliminary Assessment	Completed		4/18/2008		
Remedial Investigation and/or Feasibility Study	Completed	5/8/2008	2/11/2011		
Remedial Investigation and/or Feasibility Study	Completed	2/11/2011	12/22/2012		
Cleanup Action Plan	Completed	2/11/2011	12/22/2012		
Cleanup - Construction	Completed	6/13/2016	1/14/2017		
O & M	In Process	6/7/2017			
Order/Decree/Amendment	In Process	9/6/2017			
Order/Decree/Amendment	In Process	3/22/2019			