

Cleanup Site Details

Cleanup Site ID: 3444

Cleanup Site ID: 3444 Facility/Site ID: 93937775 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Port Gamble Bay and Mill Site [Glossary](#)

Alternate Names: DNR AQUATIC LAND LEASE AREA FORMER, Pope & Talbot Inc Sawmill, POPE & TALBOT PORT GAMBLE MILL, Port Gamble Bay & Mill Site, Port Gamble Bay and Mill Site, Port Gamble Log Storage Lease Area

LOCATION

Address: VIEW DRIVE **City:** PORT GAMBLE **Zip Code:** 98364 **County:** Kitsap
Latitude: 47.85438 **Longitude:** -122.58255 **WRIA:** 15 **Legislative District:** 23 **Congressional District:** 6 **TRS:** 27N 2E 5

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** Yes
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes
Site Rank: 2 - Moderate-High Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: King, Corey **Responsible Unit:** Headquarters **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Port Gamble Log Storage Lease Area	Sediment	Awaiting Cleanup	HQ	King, Corey	Ecology-supervised or conducted
Pope & Talbot Inc Sawmill	Sediment	Construction Complete-Performance Monitoring	HQ	King, Corey	Ecology-supervised or conducted
Pope & Talbot Inc Sawmill	Upland	Cleanup Started	HQ	King, Corey	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C	C				
Base/Neutral/Acid Organics		S				
Bioassay Benthic Failures				C		
Halogenated Organics	C	S	S	C	S	
Metals - Other	S	S		C		
Metals Priority Pollutants	C	C	S	C	S	
Other Deleterious Substances			C	C		
Petroleum Products-Unspecified	C	C			S	
Phenolic Compounds				C		
Polychlorinated biPhenyls (PCB)	C	S	S			
Polycyclic Aromatic Hydrocarbons	C	S	S	C	S	

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 3444

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Order/Decree/Amendment	In Process		
Site Discovery/Release Report Received	Completed		10/17/1996
Initial Investigation / Federal Preliminary Assessment	Completed		4/3/2000
Initial Investigation / Federal Preliminary Assessment	Completed		3/20/2001
Early Notice Letter(s)	Completed		4/11/2001
Site Hazard Assessment/Federal Site Inspection	Completed	4/18/2001	8/21/2001
Hazardous Sites Listing/NPL	Completed		8/28/2001
VCP Opinion on Cleanup Action	Canceled	3/20/2002	
Site Characterization	Completed	4/9/2003	7/9/2003
VCP Opinion on Site Cleanup	Completed	4/9/2003	7/21/2003
Remedial Investigation and/or Feasibility Study	Completed	2/1/2007	2/1/2010
Initial Investigation / Federal Preliminary Assessment	Completed		4/18/2008
Remedial Investigation and/or Feasibility Study	Completed	5/8/2008	2/11/2011
Remedial Investigation and/or Feasibility Study	Completed	2/11/2011	12/22/2012
Cleanup Action Plan	Completed	2/11/2011	12/22/2012
Cleanup - Construction	Completed	6/13/2016	1/14/2017
O & M	In Process	6/7/2017	
Order/Decree/Amendment	In Process	9/6/2017	