

Cleanup Site Details

Cleanup Site ID: 3548

Cleanup Site ID: 3548 **Facility/Site ID:** 88531932 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Art Brass Plating Inc Seattle [Glossary](#)
Alternate Names: ART BRASS PLATING INC, Art Brass Plating Inc Seattle

LOCATION

Address: 5516 3RD AVE S **City:** SEATTLE **Zip Code:** 98108 **County:** King
Latitude: 47.55283 **Longitude:** -122.33059 **WRIA:** 9 **Legislative District:** 11 **Congressional District:** 7 **TRS:** 24N 4E 20

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes
Site Rank: 3 - Moderate Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Jones, Ed **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Art Brass Plating Inc Seattle	Upland	Cleanup Started	NW	Jones, Ed	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	C	C				
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		7/21/2005
Initial Investigation / Federal Preliminary Assessment	Completed		7/21/2005
Remedial Investigation and/or Feasibility Study	Canceled	7/21/2005	12/31/2006
VCP Status Request	Completed	5/27/2008	7/1/2008
Site Hazard Assessment/Federal Site Inspection	Completed	7/24/2015	8/5/2015
Hazardous Sites Listing/NPL	Completed		8/10/2015