

Cleanup Site Details

Cleanup Site ID: 3552

Cleanup Site ID: 3552 Facility/Site ID: 1012 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Carborundum Co [Glossary](#)

Alternate Names: CARBORUNDUM CO, Port of Vancouver

LOCATION

Address: VANCOUVER PORT LOWER RIVER RD City: VANCOUVER Zip Code: 98660 County: Clark

Latitude: 45.63443 Longitude: -122.69508 WRIA: 28 Legislative District: 49 Congressional District: 3 TRS:

DETAIL

Status: No Further Action **NFA Received?** Yes **Is PSI site?** No
Statute: MTCA **NFA Date:** 3/17/1998 **Current VCP?** No **Past VCP?** No
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** Ecology Supervised/Conducted Cleanup **Brownfield?** No
Site Manager: Hayes, Mary Beth **Responsible Unit:** Southwest **Active Institutional Control?** Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CARBORUNDUM CO	Upland	No Further Action Required	SW	Hayes, Mary Beth	IRAP

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil, Groundwater	Restrict Land Use, Restrict Domestic Ground Water Extraction/Well Installation, Prohibit Soil Disturbance	2/20/1998	9802230225	Clark	059115-010-0
Environmental Covenant	Soil, Groundwater	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance	2/20/1998	9802230223	Clark	059115-010

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	RA					
Metals - Other	RA					
Polycyclic Aromatic Hydrocarbons		R				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Hazardous Sites Listing/NPL	Completed		8/27/1991
Independent Report Review - Paid	Completed	3/18/1996	3/17/1998
Remove site from Hazardous Sites List	Completed		3/17/1998
Site Status Changed to NFA	Completed		3/17/1998
Periodic Review	Completed	11/4/2011	1/17/2012

Cleanup Site Details

Cleanup Site ID: 3552

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Periodic Review	Completed	9/1/2016	12/12/2016
Periodic Review	Completed	9/1/2021	11/7/2022
Periodic Review	Planned	9/7/2027	1/1/1900