

Cleanup Site Details

Cleanup Site ID: 3618

Cleanup Site ID: 3618 Facility/Site ID: 84531356 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: USG Interiors Inc 99 Site [Glossary](#)

Alternate Names: USG HWY 99 SITE, USG Interiors Inc 99 Site

LOCATION

Address: 7110 Pacific Hwy E City: Milton Zip Code: 98354 County: Pierce
Latitude: 47.24652 Longitude: -122.33543 WRIA: 10 Legislative District: 30 Congressional District: 8 TRS: 20N 4E 5

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Misuraca, Tia Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
USG Interiors Inc 99 Site	Upland	Cleanup Started	SW	Smith, Andrew	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	R	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		1/1/1984
Cleanup - Construction	Completed	1/1/1984	12/31/1984
O & M	Completed	12/31/1984	4/1/2005
Non-LUST Ind Report Received	Completed		2/1/2007
Remedial Investigation and/or Feasibility Study	Completed	5/1/2008	6/23/2016
Order/Decree/Amendment	Completed	10/18/2009	6/24/2016
Non-LUST Ind Report Received	Completed		12/22/2009
Non-LUST Ind Report Received	Completed		3/10/2010
Cleanup Action Plan	Completed	10/11/2013	6/23/2016
Order/Decree/Amendment	In Process	12/1/2014	

Cleanup Site Details

Cleanup Site ID: 3618

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Non-LUST Ind Report Received	Completed		10/31/2016
Cleanup Action - Engineering Design	In Process	7/1/2017	