

Cleanup Site Details

Cleanup Site ID: 3618

Cleanup Site ID: 3618 **Facility/Site ID:** 84531356 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: USG Interiors Inc 99 Site [Glossary](#)
Alternate Names: USG HWY 99 SITE, USG Interiors Inc 99 Site

LOCATION

Address: 7110 Pacific Hwy E **City:** Milton **Zip Code:** 98354 **County:** Pierce
Latitude: 47.24652 **Longitude:** -122.33543 **WRIA:** 10 **Legislative District:** 30 **Congressional District:** 8 **TRS:** 20N 4E 5

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No
Site Manager: Misuraca, Tia **Responsible Unit:** Southwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
USG Interiors Inc 99 Site	Upland	Cleanup Started	SW	Smith, Andrew	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	R	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		1/1/1984
Cleanup - Construction	Completed	1/1/1984	12/31/1984
O & M	Completed	12/31/1984	4/1/2005
Non-LUST Ind Report Received	Completed		2/1/2007
Remedial Investigation and/or Feasibility Study	Completed	5/1/2008	6/23/2016
Order/Decree/Amendment	Completed	10/18/2009	6/24/2016
Non-LUST Ind Report Received	Completed		12/22/2009
Non-LUST Ind Report Received	Completed		3/10/2010
Cleanup Action Plan	Completed	10/11/2013	6/23/2016
Order/Decree/Amendment	In Process	12/1/2014	

Cleanup Site Details

Cleanup Site ID: 3618

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Non-LUST Ind Report Received	Completed		10/31/2016
Cleanup Action - Engineering Design	In Process	7/1/2017	