

# Cleanup Site Details

Cleanup Site ID: 3618

**Cleanup Site ID:** 3618      **Facility/Site ID:** 84531356      **UST ID:** N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)  
**Cleanup Site Name:** USG Interiors Inc 99 Site      [Glossary](#)  
**Alternate Names:** USG HWY 99 SITE, USG Interiors Inc 99 Site

## LOCATION

**Address:** 7110 Pacific Hwy E      **City:** Milton      **Zip Code:** 98354      **County:** Pierce  
**Latitude:** 47.24652      **Longitude:** -122.33543      **WRIA:** 10      **Legislative District:** 30      **Congressional District:** 8      **TRS:** 20N 4E 5

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** No  
**Site Rank:** N/A      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Misuraca, Tia      **Responsible Unit:** Southwest      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
USG Interiors Inc 99 Site	Upland	Cleanup Started	SW	Smith, Andrew	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	R	C				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		1/1/1984
Cleanup - Construction	Completed	1/1/1984	12/31/1984
O & M	Completed	12/31/1984	4/1/2005
Non-LUST Ind Report Received	Completed		2/1/2007
Remedial Investigation and/or Feasibility Study	Completed	5/1/2008	6/23/2016
Order/Decree/Amendment	Completed	10/18/2009	6/24/2016
Non-LUST Ind Report Received	Completed		12/22/2009
Non-LUST Ind Report Received	Completed		3/10/2010
Cleanup Action Plan	Completed	10/11/2013	6/23/2016
Order/Decree/Amendment	In Process	12/1/2014	

# Cleanup Site Details

Cleanup Site ID: 3618

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Non-LUST Ind Report Received	Completed		10/31/2016
Cleanup Action - Engineering Design	In Process	7/1/2017	