

Cleanup Site Details

Cleanup Site ID: 3632

Cleanup Site ID: 3632 Facility/Site ID: 500 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: Yakima Railroad Glossary

Alternate Names: Yakima Railroad

LOCATION

Address: 1ST ST CORRIDOR City: YAKIMA Zip Code: 98901 County: Yakima

Latitude: 46.61097 Longitude: -120.51088 WRIA: 37 Legislative District: 15 Congressional District: 4 TRS: 13N 18E 13

DETAIL

Status: Construction Complete- NFA Received? No Is PSI site? No

Performance Monitoring

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Lind, Jennifer Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Yakima Railroad	Upland	Construction Complete- Performance Monitoring	CE	Lind, Jennifer	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
mstrument Type	Media	Date	Number	County	١,

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Solvents	С	С			S	

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Order/Decree/Amendment	Completed		1/1/1900
Order/Decree/Amendment	Completed		1/1/1900
Order/Decree/Amendment	In Process		
Order/Decree/Amendment	Completed	2/11/1992	1/1/1900
Order/Decree/Amendment	Completed	8/28/1992	1/1/1900
Order/Decree/Amendment	Completed	1/28/1993	1/1/1900
Remedial Investigation and/or Feasibility Study	Completed	6/1/1995	7/29/1999
Order/Decree/Amendment	In Process	7/19/1995	

Toxics Cleanup Program Report Generated: 11/14/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Cleanup - Performance Monitoring	In Process	7/29/1999	

Cleanup Site ID: 3632