

Cleanup Site Details

Cleanup Site ID: 3643
Cleanup Site ID: 3643 **Facility/Site ID:** 1222 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: McFarland Cascade Pole & Lumber Co [Glossary](#)
Alternate Names: CASCADE POLE BLAIR WATERWAY, CASCADE POLE CO, McFarland Cascade Pole & Lumber Co

LOCATION
Address: 1640 E MARC ST **City:** TACOMA **Zip Code:** 98421 **County:** Pierce
Latitude: 47.25675 **Longitude:** -122.41058 **WRIA:** 10 **Legislative District:** 27 **Congressional District:** 9 **TRS:** 20N 3E 3

DETAIL

Status: Cleanup Complete-Active O&M/Monitoring	NFA Received? No	Is PSI site? Yes
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: 1 - Highest Assessed Risk	NFA Reason: N/A	Brownfield? No
Site Manager: Kaufmann, Ron	Responsible Unit: Hazardous Waste	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
McFarland Cascade Pole & Lumber Co	Upland	Cleanup Complete-Active O&M/Monitoring ongoing	HWTR	Kaufmann, Ron	Ecology-supervised or conducted
2014 Spill	Upland	No Further Action Required	SW	Wecker, Kirsten	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics	C	C				
Metals - Other	RB					
Metals Priority Pollutants	C	C	C		S	
Non-Halogenated Solvents	S	S	S		S	
Phenolic Compounds	C	C	C		S	
Polycyclic Aromatic Hydrocarbons	C	C	C		S	

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Site Hazard Assessment/Federal Site Inspection	Completed	5/1/1990	8/1/1990
Hazardous Sites Listing/NPL	Completed		9/10/1990

Cleanup Site Details

Cleanup Site ID: 3643

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Remedial Investigation and/or Feasibility Study	Completed	1/4/1992	12/30/2001
Interim Action	Completed	6/7/1993	11/10/1993
Interim Action	Completed	1/30/1995	12/30/1998
Interim Action	Completed	11/1/1998	12/30/1999
Initial Investigation / Federal Preliminary Assessment	Completed		12/11/2014