

# Cleanup Site Details

Cleanup Site ID: 3646

**Cleanup Site ID:** 3646      **Facility/Site ID:** 1247      **UST ID:** N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)  
**Cleanup Site Name:** Sound Battery aka: Allied Battery Co Inc Tacoma      [Glossary](#)  
**Alternate Names:** ALLIED BATTERY CO INC 11TH ST, Allied Battery Co Inc Tacoma, ALLIED BATTERY CO TACOMA, Sound Battery aka: Allied Battery Co Inc Tacoma, SOUND BATTERY CO INC

## LOCATION

**Address:** 2310 E 11TH ST      **City:** TACOMA      **Zip Code:** 98421      **County:** Pierce  
**Latitude:** 47.26672      **Longitude:** -122.40852      **WRIA:** 10      **Legislative District:** 27      **Congressional District:** 9      **TRS:** 21N 3E 34

## DETAIL

**Status:** No Further Action      **NFA Received?** Yes      **Is PSI site?** Yes  
**Statute:** MTCA      **NFA Date:** 5/15/2018      **Current VCP?** No      **Past VCP?** Yes  
**Site Rank:** 0 - NPL Site (Fed HRS Score)      **NFA Reason:** Voluntary Cleanup Program Review      **Brownfield?** No  
**Site Manager:** Middleton, Tom      **Responsible Unit:** Southwest      **Active Institutional Control?** Yes

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Allied Battery Co Inc Tacoma	Upland	No Further Action Required	SW	Middleton, Tom	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation, Maintain/Protect Monitoring System	2/3/2017	201702030329	Pierce	227-5200770

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Lead	RB	RB				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Remedial Investigation and/or Feasibility Study	Completed	3/1/1991	5/1/1991
Cleanup Action Plan	Canceled	6/1/1993	4/1/1996
Remedial Investigation and/or Feasibility Study	Completed	6/1/1993	12/15/1993
Hazardous Sites Listing/NPL	Completed		9/7/1993
Cleanup Action - Engineering Design	Canceled	4/5/1994	7/1/1996
Cleanup - Construction	Canceled	4/5/1994	11/1/1996
Remedial Investigation and/or Feasibility Study	Completed	6/11/1997	3/1/2000
Cleanup Action Plan	Completed	6/11/1999	12/30/2001

# Cleanup Site Details

Cleanup Site ID: 3646

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Order/Decree/Amendment	Completed	2/15/2001	6/3/2003
Cleanup - Construction	Completed	4/1/2002	10/30/2002
Remove site from Hazardous Sites List	Completed		5/21/2003
Site Status Changed to NFA	Completed		5/21/2003
Site Discovery/Release Report Received	Completed		2/21/2012
Reopen Site	Completed		2/21/2012
VCP Receipt of Plan or Report	Completed		6/26/2014
VCP Opinion on Site Cleanup Plan	Completed	8/4/2014	9/11/2014
VCP Receipt of Plan or Report	Completed		7/30/2015
VCP Opinion on Site Cleanup Plan	Completed	7/30/2015	10/23/2017
Remove site from Hazardous Sites List	Completed		5/15/2018
Site Status Changed to NFA	Completed		5/15/2018
Non-LUST Ind Report Received	Completed		2/7/2020
Periodic Review	Planned	5/15/2023	