

# Cleanup Site Details

Cleanup Site ID: 3672

<b>Cleanup Site ID:</b> 3672	<b>Facility/Site ID:</b> 1224	<b>UST ID:</b> 4415	<a href="#">Site Page</a>	<a href="#">Site Documents</a>	<a href="#">View Map</a>	
<b>Cleanup Site Name:</b> Tacoma Boatbuilding Ace Tank					<a href="#">Glossary</a>	
<b>Alternate Names:</b> ACE TANK & EQUIPMENT, ACE TANK & EQUIPMENT CO TACOMA OPERATION, ACETANK & EQUIPMENT DBA ACE MANUFAC, Busby Marine & Tank Inc, TACOMA BOAT BUILDING CO, Tacoma Boatbuilding Ace Tank, TACOMA BOATBUILDING CO						
<b>LOCATION</b>						
<b>Address:</b> 1840 MARINE VIEW DR		<b>City:</b> TACOMA	<b>Zip Code:</b> 98422	<b>County:</b> Pierce		
<b>Latitude:</b> 47.26751	<b>Longitude:</b> -122.36408	<b>WRIA:</b> 10	<b>Legislative District:</b> 27	<b>Congressional District:</b> 9	<b>TRS:</b> 21N 3E 36	
<b>DETAIL</b>						
<b>Status:</b> Cleanup Complete-Active O&M/Monitoring	<b>NFA Received?</b> No	<b>Is PSI site?</b> Yes				
<b>Statute:</b> MTCA	<b>NFA Date:</b> N/A	<b>Current VCP?</b> No		<b>Past VCP?</b> No		
<b>Site Rank:</b> N/A	<b>NFA Reason:</b> N/A	<b>Brownfield?</b> No				
<b>Site Manager:</b> Balaraju, Panjini	<b>Responsible Unit:</b> Southwest	<b>Active Institutional Control?</b>		Yes		
<b>CLEANUP UNITS</b>						
<b>Cleanup Unit Name</b>	<b>Unit Type</b>	<b>Unit Status</b>	<b>Resp Unit</b>	<b>Unit Manager</b>	<b>Current Process</b>	
TACOMA BOAT/ACE TANK	Upland	Cleanup Complete-Active O&M/Monitoring ongoing	SW	Balaraju, Panjini	Ecology-supervised or conducted	
<b>ACTIVE INSTITUTIONAL CONTROLS</b>						
<b>Instrument Type</b>	<b>Restriction Media</b>	<b>Restrictions/Requirements</b>	<b>Date</b>	<b>Recording Number</b>	<b>Recording County</b>	<b>Tax Parcel</b>
Environmental Covenant	Soil, Sediment	Restrict Land Use, Prohibit Soil Disturbance	11/19/1999	9911190310	Pierce	0321361800
Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the <a href="#">Environmental Covenants Registry List</a> .						
<b>AFFECTED MEDIA &amp; CONTAMINANTS</b>						
<b>MEDIA</b>						
<b>Contaminant</b>	<b>Soil</b>	<b>Groundwater</b>	<b>Surface Water</b>	<b>Sediment</b>	<b>Air</b>	<b>Bedrock</b>
Metals Priority Pollutants			R			
Petroleum-Other	C					
<b>Key:</b> B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above S - Suspected                      R - Remediated                      RB - Remediated-Below						
<b>SITE ACTIVITIES</b>						
<b>Activity</b>	<b>Status</b>		<b>Start Date</b>	<b>End Date/ Completion Date</b>		
Site Discovery/Release Report Received	Completed			3/1/1988		
LUST - Notification	Completed			3/1/1995		
LUST - Report Received	Completed			8/29/1995		
Order/Decree/Amendment	Completed		9/7/1995	1/1/1900		
Order/Decree/Amendment	In Process		10/2/1996			
Cleanup Action Plan	Completed		6/8/1998	10/22/1999		
Cleanup - Construction	Completed		8/20/1998	10/20/1998		
<b>Toxics Cleanup Program</b> <span style="float: right;"><b>Report Generated: 8/17/2025</b></span> <span style="float: right;"><b>Page 1 of 2</b></span>						

# Cleanup Site Details

Cleanup Site ID: 3672

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Periodic Review	Completed	5/15/2008	9/6/2011
Periodic Review	Completed	5/2/2016	8/8/2016
Periodic Review	Completed	5/1/2021	12/3/2023
Periodic Review	Planned	10/3/2028	1/1/1900