

Cleanup Site Details

Cleanup Site ID: 3672

Cleanup Site ID: 3672 Facility/Site ID: 1224 UST ID: 4415 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Tacoma Boatbuilding Ace Tank

[Glossary](#)

Alternate Names: ACE TANK & EQUIPMENT, ACE TANK & EQUIPMENT CO TACOMA OPERATION, ACETANK & EQUIPMENT DBA ACE MANUFAC, Busby Marine & Tank Inc, TACOMA BOAT BUILDING CO, Tacoma Boatbuilding Ace Tank, TACOMA BOATBUILDING CO

LOCATION

Address: 1840 MARINE VIEW DR **City:** TACOMA **Zip Code:** 98422 **County:** Pierce
Latitude: 47.26751 **Longitude:** -122.36408 **WRIA:** 10 **Legislative District:** 27 **Congressional District:** 9 **TRS:** 21N 3E 36

DETAIL

Status: Cleanup Complete-Active O&M/Monitoring	NFA Received? No	Is PSI site? Yes
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: N/A	Brownfield? No
Site Manager: Balaraju, Panjini	Responsible Unit: Southwest	Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
TACOMA BOAT/ACE TANK	Upland	Cleanup Complete-Active O&M/Monitoring ongoing	SW	Balaraju, Panjini	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil, Sediment	Restrict Land Use, Prohibit Soil Disturbance	11/19/1999	9911190310	Pierce	0321361800

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants			R			
Petroleum-Other	C					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
LUST - Notification	Completed		3/1/1995
LUST - Report Received	Completed		8/29/1995
Order/Decree/Amendment	Completed	9/7/1995	1/1/1900
Order/Decree/Amendment	In Process	10/2/1996	
Cleanup Action Plan	Completed	6/8/1998	10/22/1999
Cleanup - Construction	Completed	8/20/1998	10/20/1998

Cleanup Site Details

Cleanup Site ID: 3672

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Periodic Review	Completed	5/15/2008	9/6/2011
Periodic Review	Completed	5/2/2016	8/8/2016
Periodic Review	Completed	5/1/2021	12/3/2023
Periodic Review	Planned	10/3/2028	1/1/1900