

Cleanup Site Details

Cleanup Site ID: 3689

Cleanup Site ID: 3689 Facility/Site ID: 2382 UST ID: 6163 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Jorgensen Forge Corp [Glossary](#)

Alternate Names: EARLE M JORGENSEN COMPANY, JORGENSEN FORGE AREA 3 GASOLINE, Jorgensen Forge Corp, MINERALIZED CELL WOOD PRES CO, STAR FORGE DBA JORGENSEN FORGE LLC

LOCATION

Address: 8531 E MARGINAL WAY S **City:** TUKWILA **Zip Code:** 98108 **County:** King
Latitude: 47.52624 **Longitude:** -122.30502 **WRIA:** 9 **Legislative District:** 11 **Congressional District:** 9 **TRS:** 24N 4E 33

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Johnson, Beau **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Jorgensen Forge Corp	Upland	Cleanup Started	NW	Johnson, Beau	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic		C				
Halogenated Solvents	S	C				
Lead		C				
Metals - Other	C	C				
Metals Priority Pollutants	C					
Non-Halogenated Solvents	C	C				
Per- and polyfluoroalkyl substances (PFAS)		C				
Petroleum Products-Unspecified	C	C				
Polychlorinated biPhenyls (PCB)	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		7/10/1991

Cleanup Site Details

Cleanup Site ID: 3689

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Early Notice Letter(s)	Completed		1/17/1992
Remedial Investigation and/or Feasibility Study	Canceled	6/1/1993	3/1/1994
Site Hazard Assessment/Federal Site Inspection	Completed	6/15/1993	8/25/1993
Hazardous Sites Listing/NPL	Completed		8/25/1993
VCP Opinion on Cleanup Action	Completed	9/13/1999	6/8/2006
Site Hazard Assessment/Federal Site Inspection	Completed	4/5/2005	7/29/2005
Order/Decree/Amendment	Completed	7/1/2007	1/1/2014
Remedial Investigation and/or Feasibility Study	Completed	7/12/2007	12/31/2009
Federal Emergency Response/Time-Critical Removal Action	Completed	1/1/2010	5/11/2018
Interim Action - Plan	Completed	4/1/2013	7/1/2013
Order/Decree/Amendment	Canceled	1/1/2014	1/1/2015
Interim Action - Construction	Completed	6/30/2014	10/30/2014
Order/Decree/Amendment	In Process	12/1/2016	
Remedial Investigation and/or FS Work Plan	In Process	2/1/2018	
Federal Non-Time Critical Removal Action	In Process	6/22/2018	