

# Cleanup Site Details

Cleanup Site ID: 3689

Cleanup Site ID: 3689      Facility/Site ID: 2382      UST ID: 6163      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Jorgensen Forge Corp      [Glossary](#)

**Alternate Names:** EARLE M JORGENSEN COMPANY, JORGENSEN FORGE AREA 3 GASOLINE, Jorgensen Forge Corp, Mineralized Cell Wood Pres Co, STAR FORGE DBA JORGENSEN FORGE LLC

## LOCATION

**Address:** 8531 E MARGINAL WAY S      **City:** TUKWILA      **Zip Code:** 98108      **County:** King  
**Latitude:** 47.52624      **Longitude:** -122.30502      **WRIA:** 9      **Legislative District:** 11      **Congressional District:** 9      **TRS:** 24N 4E 33

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** Yes  
**Site Rank:** 1 - Highest Assessed Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Johnson, Beau      **Responsible Unit:** Northwest      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Jorgensen Forge Corp	Upland	Cleanup Started	NW	Johnson, Beau	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic		C				
Halogenated Solvents	S	C				
Lead		C				
Metals - Other	C	C				
Metals Priority Pollutants	C					
Non-Halogenated Solvents	C	C				
Per- and polyfluoroalkyl substances (PFAS)		C				
Petroleum Products-Unspecified	C	C				
Polychlorinated biPhenyls (PCB)	C	C				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		7/10/1991

# Cleanup Site Details

Cleanup Site ID: 3689

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Early Notice Letter(s)	Completed		1/17/1992
Remedial Investigation and/or Feasibility Study	Canceled	6/1/1993	3/1/1994
Site Hazard Assessment/Federal Site Inspection	Completed	6/15/1993	8/25/1993
Hazardous Sites Listing/NPL	Completed		8/25/1993
VCP Opinion on Cleanup Action	Completed	9/13/1999	6/8/2006
Site Hazard Assessment/Federal Site Inspection	Completed	4/5/2005	7/29/2005
Order/Decree/Amendment	Completed	7/1/2007	1/1/2014
Remedial Investigation and/or Feasibility Study	Completed	7/12/2007	12/31/2009
Federal Emergency Response/Time-Critical Removal Action	Completed	1/1/2010	5/11/2018
Interim Action - Plan	Completed	4/1/2013	7/1/2013
Order/Decree/Amendment	Canceled	1/1/2014	1/1/2015
Interim Action - Construction	Completed	6/30/2014	10/30/2014
Order/Decree/Amendment	In Process	12/1/2016	
Remedial Investigation and/or FS Work Plan	In Process	2/1/2018	
Federal Non-Time Critical Removal Action	In Process	6/22/2018	