

Cleanup Site Details

Cleanup Site ID: 3718

Cleanup Site ID: 3718	Facility/Site ID: 359	UST ID: N/A	Site Page	Site Documents	View Map	
Cleanup Site Name: Rons Automotive Leavenworth					Glossary	
Alternate Names: RONS AUTOMOTIVE LEAVENWORTH						
LOCATION						
Address: 1320 US HWY 2		City: LEAVENWORTH	Zip Code: 98826	County: Chelan		
Latitude: 47.59886	Longitude: -120.65563	WRIA: 45	Legislative District: 12	Congressional District: 8	TRS: 24N 17E 1	
DETAIL						
Status: No Further Action	NFA Received? Yes	Is PSI site? No				
Statute: MTCA	NFA Date: 6/29/1995	Current VCP? No		Past VCP? No		
Site Rank: N/A	NFA Reason: Site Hazard Assessment	Brownfield? No				
Site Manager: Central Region	Responsible Unit: Central	Active Institutional Control?		No		
CLEANUP UNITS						
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
Rons Automotive Leavenworth	Upland	No Further Action Required	CE	Central Region	Independent Action	
ACTIVE INSTITUTIONAL CONTROLS						
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						
AFFECTED MEDIA & CONTAMINANTS						
MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified	B					
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						
SITE ACTIVITIES						
Activity	Status		Start Date	End Date/ Completion Date		
Site Hazard Assessment	Completed		4/3/1995	6/29/1995		
Site Status Changed to NFA	Completed			6/29/1995		