

# Cleanup Site Details

Cleanup Site ID: 3783

Cleanup Site ID: 3783      Facility/Site ID: 1043      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)  
 Cleanup Site Name: Chevron Bulk Plant Camas      [Glossary](#)  
 Alternate Names: CHEVRON BULK PLANT CAMAS, TRIANGLE RESOURCES

**LOCATION**  
 Address: 612 SE Union Street      City: CAMAS      Zip Code: 98607      County: Clark  
 Latitude: 45.58285      Longitude: -122.38524      WRIA: 28      Legislative District: 18      Congressional District: 3      TRS: 1N 3E 48

**DETAIL**  
 Status: No Further Action      NFA Received? Yes      Is PSI site? No  
 Statute: MTCA      NFA Date: 9/25/2019      Current VCP? No      Past VCP? No  
 Site Rank: 2 - Moderate-High Risk      NFA Reason: Ecology Supervised/Conducted Cleanup      Brownfield? No  
 Site Manager: Rankine, Craig      Responsible Unit: Southwest      Active Institutional Control? No

**CLEANUP UNITS**

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CHEVRON BULK PLANT CAMAS	Upland	No Further Action Required	SW	Rankine, Craig	Ecology-supervised or conducted

**ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

**AFFECTED MEDIA & CONTAMINANTS**

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics		RB				
Metals Priority Pollutants	RB					
Non-Halogenated Solvents	RB	RB				
Petroleum Products-Unspecified	RB	RB				

**Key:**  
 B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
 S - Suspected      R - Remediated      RB - Remediated-Below

**SITE ACTIVITIES**

Activity	Status	Start Date	End Date/Completion Date
Order/Decree/Amendment	Completed	1/1/1994	9/25/2019
Site Hazard Assessment/Federal Site Inspection	Completed	2/10/1995	6/29/1995
Hazardous Sites Listing/NPL	Completed		8/22/1995
Remedial Investigation and/or Feasibility Study	Completed	10/20/2003	2/26/2018
Cleanup Action Plan	Completed	12/1/2017	7/6/2018
Remove site from Hazardous Sites List	Completed		9/25/2019

# Cleanup Site Details

Cleanup Site ID: 3783

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Site Status Changed to NFA	Completed		9/25/2019