

Cleanup Site Details

Cleanup Site ID: 3783

Cleanup Site ID: 3783
Facility/Site ID: 1043
UST ID: N/A
[Site Page](#)
[Site Documents](#)
[View Map](#)
Cleanup Site Name: Chevron Bulk Plant Camas
[Glossary](#)
Alternate Names: CHEVRON BULK PLANT CAMAS, TRIANGLE RESOURCES

LOCATION

Address: 612 SE Union Street
City: CAMAS
Zip Code: 98607
County: Clark
Latitude: 45.58285
Longitude: -122.38524
WRIA: 28
Legislative District: 18
Congressional District: 3
TRS: 1N 3E 48

DETAIL

Status: No Further Action
NFA Received? Yes
Is PSI site? No
Statute: MTCA
NFA Date: 9/25/2019
Current VCP? No
Past VCP? No
Site Rank: 2 - Moderate-High Risk
NFA Reason: Ecology Supervised/Conducted Cleanup
Brownfield? No
Site Manager: Rankine, Craig
Responsible Unit: Southwest
Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CHEVRON BULK PLANT CAMAS	Upland	No Further Action Required	SW	Rankine, Craig	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics		RB				
Metals Priority Pollutants	RB					
Non-Halogenated Solvents	RB	RB				
Petroleum Products-Unspecified	RB	RB				

Key:
B - Below Cleanup Level
C - Confirmed Above Cleanup Level
RA - Remediated-Above
S - Suspected
R - Remediated
RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Order/Decree/Amendment	Completed	1/1/1994	9/25/2019
Site Hazard Assessment/Federal Site Inspection	Completed	2/10/1995	6/29/1995
Hazardous Sites Listing/NPL	Completed		8/22/1995
Remedial Investigation and/or Feasibility Study	Completed	10/20/2003	2/26/2018
Cleanup Action Plan	Completed	12/1/2017	7/6/2018
Remove site from Hazardous Sites List	Completed		9/25/2019

Cleanup Site Details

Cleanup Site ID: 3783

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Status Changed to NFA	Completed		9/25/2019