

Cleanup Site Details

Cleanup Site ID: 3783 Facility/Site ID: 1043 UST ID: N/A Site Page **Site Documents** View Map

Cleanup Site ID: 3783

Cleanup Site Name: Chevron Bulk Plant Camas **Glossary**

Alternate Names: CHEVRON BULK PLANT CAMAS, TRIANGLE RESOURCES

LOCATION

Address: 612 SE Union Street City: CAMAS **Zip Code:** 98607 County: Clark

Latitude: 45.58285 Longitude: -122.38524 **WRIA**: 28 Legislative District: 18 Congressional District: 3 **TRS**: 1N 3E 48

DETAIL

NFA Received? Is PSI site? Status: No Further Action Yes No

MTCA NFA Date: 9/25/2019 Current VCP? Past VCP? No Statute: No

Ecology Supervised/Conducted Site Rank: 2 - Moderate-High Risk NFA Reason: **Brownfield?** No

Cleanup

Active Institutional Control? Site Manager: Rankine, Craig Responsible Unit: Southwest No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CHEVRON BULK PLANT CAMAS	Upland	No Further Action Required	SW	Rankine, Craig	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Halogenated Organics		RB					
Metals Priority Pollutants	RB						
Non-Halogenated Solvents	RB	RB					
Petroleum Products-Unspecified	RB	RB					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level

RA - Remediated-Above RB - Remediated-Below S - Suspected R - Remediated

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	Completed	1/1/1994	9/25/2019
Site Hazard Assessment	Completed	2/10/1995	6/29/1995
Hazardous Sites Listing	Completed		8/22/1995
Remedial Investigation and/or Feasibility Study	Completed	10/20/2003	2/26/2018
Cleanup Action Plan	Completed	12/1/2017	7/6/2018
Remove site from Hazardous Sites List	Completed		9/25/2019

Toxics Cleanup Program Report Generated: 7/3/2025 Page 1 of 2



Cleanup Site Details

Cleanup Site ID: 3783

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Site Status Changed to NFA	Completed		9/25/2019			

Toxics Cleanup Program Report Generated: 7/3/2025 Page 2 of 2