

## Cleanup Site Details

Cleanup Site ID: 3783

Cleanup Site ID: 3783 Facility/Site ID: 1043 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: Chevron Bulk Plant Camas

Alternate Names: CHEVRON BULK PLANT CAMAS, TRIANGLE RESOURCES

LOCATION

Address: 612 SE Union Street City: CAMAS Zip Code: 98607 County: Clark

Latitude: 45.58285 Longitude: -122.38524 WRIA: 28 Legislative District: 18 Congressional District: 3 TRS: 1N 3E 48

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 9/25/2019 Current VCP? No Past VCP? No

Site Rank: 2 - Moderate-High Risk NFA Reason: Ecology Supervised/Conducted Brownfield? No

Cleanup

Site Manager: Rankine, Craig Responsible Unit: Southwest Active Institutional Control? No

**CLEANUP UNITS** 

| Cleanup Unit Name        | Unit Type | Unit Status                | Resp<br>Unit Manager |                | Current Process                 |
|--------------------------|-----------|----------------------------|----------------------|----------------|---------------------------------|
| CHEVRON BULK PLANT CAMAS | Upland    | No Further Action Required | SW                   | Rankine, Craig | Ecology-supervised or conducted |

#### **ACTIVE INSTITUTIONAL CONTROLS**

| Instrument Type | Restrictions/Requirements | nstrument Type Restriction Media | Date | Recording<br>Number | Recording County | Tax Parcel |
|-----------------|---------------------------|----------------------------------|------|---------------------|------------------|------------|
|-----------------|---------------------------|----------------------------------|------|---------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

#### **AFFECTED MEDIA & CONTAMINANTS**

|                                | MEDIA |             |               |          |     |         |  |
|--------------------------------|-------|-------------|---------------|----------|-----|---------|--|
| Contaminant                    | Soil  | Groundwater | Surface Water | Sediment | Air | Bedrock |  |
| Halogenated Organics           |       | RB          |               |          |     |         |  |
| Metals Priority Pollutants     | RB    |             |               |          |     |         |  |
| Non-Halogenated Solvents       | RB    | RB          |               |          |     |         |  |
| Petroleum Products-Unspecified | RB    | RB          |               |          |     |         |  |

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level S - Suspected R - Remediated

RA - Remediated-Above RB - Remediated-Below

### SITE ACTIVITIES

| Activity  | Status    | Start Date | End Date/<br>Completion Date |
|---|-----------|------------|------------------------------|
| Order/Decree/Amendment                          | Completed | 1/1/1994   | 9/25/2019                    |
| Site Hazard Assessment                          | Completed | 2/10/1995  | 6/29/1995                    |
| Hazardous Sites Listing                         | Completed |            | 8/22/1995                    |
| Remedial Investigation and/or Feasibility Study | Completed | 10/20/2003 | 2/26/2018                    |
| Cleanup Action Plan                             | Completed | 12/1/2017  | 7/6/2018                     |
| Remove site from Hazardous Sites List           | Completed |            | 9/25/2019                    |

Toxics Cleanup Program Report Generated: 11/14/2025 Page 1 of 2



# Cleanup Site Details

| SITE ACTIVITIES            |           |            |                              |  |  |
|----------------------------|-----------|------------|------------------------------|--|--|
| Activity                   | Status    | Start Date | End Date/<br>Completion Date |  |  |
| Site Status Changed to NFA | Completed |            | 9/25/2019                    |  |  |

Cleanup Site ID: 3783