	DEPARTMENT	OF
	ECOLOC	iY
	State of Washing	

Cleanup Site Details

Cleanup Site ID: 3811

Cleanup Site ID: 38	B11 Facili	Facility/Site ID: 2869			UST ID: N/A			Site	Site Documents		<u>/iew Map</u>		
Cleanup Site Name: Crosby & Overton Inc Humbolt Glossary													
Alternate Names: CROSBY & OVERTON INC HUMBOLT													
LOCATION													
Address: 2032 HUN	MBOLDT ST			City: BELLINGHAM Zip Co			ode: 982	ode: 98225 County: Whatcom					
Latitude: 48.75672 Longitude: -122.46741 WRIA: Legislative District: 42 Congressional District: 2 TRS: 38N 3E 30													
DETAIL													
Status: No Furthe	atus: No Further Action NFA Received?			Yes Is PSI site? No									
Statute: Pre-MTC	Statute: Pre-MTCA NFA Date:			9/13/1995 Current VCP? No Past VCP? No									
Site Rank: N/A NFA Reason:				Cleaned up under Prior Authority Brownfield? No									
Site Manager: Northwest Region Responsible Un			onsible Unit:	Northwest			Acti	ve Insti	tutional Cor	trol?	No		
CLEANUP UNITS													
Cleanup Ur	nit Name	Unit Type Unit S		Status	Resp Unit		Unit Manager		Current Process				
CROSBY & OVERTO HUMBOLT	DN INC	Upland	No Further A	ction Required	NW	Northy	vest Regio	egion No Process			3		
ACTIVE INSTITUTIONAL CONTROLS													
Instrument Type	Restriction Media	Restr	ictions/Requi	rements		Date Recordin Number			Recording County		ax Parcel		
There are no current Institutional Controls in effect for this site.													
AFFECTED MEDIA 8	& CONTAMINANT	S											
						MEDIA							
Contaminant			So	il Ground	water	Surface	Water	Sedim	ent Ai	r	Bedrock		
Halogenated Organic	S		В										
Key:B - Below Cleanup LevelC - Confirmed Above Cleanup LevelRA - Remediated-AboveS - SuspectedR - RemediatedRB - Remediated-Below													
SITE ACTIVITIES													
Activity						Status		Start Date		End Date/ Completion Date			
Site Discovery/Release Report Received				C	Completed			3/1/1988					
Site Status Changed to NFA Completed 9/							9/1:	3/1995					