

Cleanup Site Details

Cleanup Site ID: 3814 Facility/Site ID: 1308202 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 3814

Cleanup Site Name: Garfield Elementary School Glossary

Alternate Names: Garfield Elementary School

LOCATION

Address: 612 N 6TH AVE City: YAKIMA Zip Code: 98902 County: Yakima

Latitude: 46.61427 Longitude: -120.51980 WRIA: 37 Legislative District: 15 Congressional District: 4 TRS: 13N 18E 13

DETAIL

Status: Construction Complete- NFA Received? No Is PSI site? No

Performance Monitoring

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Central Region Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Garfield Elementary School
 Upland
 Construction Complete-Performance Monitoring
 CE
 Central Region
 Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	С					
Metals Priority Pollutants	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		4/11/2005
Early Notice Letter(s)	Completed		9/30/2005
Initial Investigation / Federal Preliminary Assessment	Completed		10/4/2005
Interim Action	Completed	4/1/2010	8/30/2010
Periodic Review	Planned	10/14/2022	12/16/2022

Toxics Cleanup Program Report Generated: 11/6/2025 Page 1 of 1