

Cleanup Site Details

Cleanup Site ID: 3862

Cleanup Site ID: 3862 Facility/Site ID: 2696 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Everett Landfill Tire Fire [Glossary](#)

Alternate Names: EVERETT CITY OF LANDFILL, EVERETT LANDFILL TIRE FIRE

LOCATION

Address: 2900 36TH ST City: EVERETT Zip Code: 98201 County: Snohomish
Latitude: 47.97000 Longitude: -122.19237 WRIA: 7 Legislative District: 38 Congressional District: 2 TRS: 29N 5E 29

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No
Site Manager: Becker, Sunny Responsible Unit: Northwest Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Everett Landfill Tire Fire	Upland	Cleanup Started	NW	Becker, Sunny	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Amended Environmental Covenant	Groundwater, Soil	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance, Ongoing Maintenance of Remedy, Prohibit Removal or Alteration of Existing Buildings	5/14/2008	200805140922	Snohomish	29053200101200

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics	C	C	C		C	
Conventional Contaminants, Inorganic	S	S	S		S	
Conventional Contaminants, Organic	C	C	C		S	
Metals - Other	S	S	S			
Metals Priority Pollutants	C	C	C		C	
Pesticides-Unspecified	S	S	S			
Petroleum Products-Unspecified	C	C	C		S	
Phenolic Compounds	S	S	S			
Polychlorinated biPhenyls (PCB)	C	S	S		C	
Polycyclic Aromatic Hydrocarbons	C	C	C		S	

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 3862

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Remedial Investigation and/or Feasibility Study	Completed	7/1/1990	12/31/1993
Site Discovery/Release Report Received	Completed		12/31/1993
Interim Action	Completed	6/13/1994	11/1/1995
Remedial Investigation and/or Feasibility Study	Completed	6/13/1994	5/1/1996
Hazardous Sites Listing/NPL	Completed		11/1/1995
Cleanup Action Plan	Completed	11/1/1996	2/28/2001
Interim Action	Completed	8/1/1997	6/30/1998
O & M	Completed	6/30/1998	1/1/2003
Order/Decree/Amendment	In Process	3/1/2000	
O & M	In Process	1/1/2003	