

Cleanup Site Details

Cleanup Site ID: 3897

Cleanup Site ID: 3897	Facility/Site ID: 55552156	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Willina Ranch					Glossary
Alternate Names: FUTTEN PROPERTIES, KNUTSEN DAIRY, WILLINA RANCH					

LOCATION

Address: 15915 115TH AVE NE			City: BOTHELL	Zip Code: 98011	County: King
Latitude: 47.74206	Longitude: -122.18884	WRIA: 8	Legislative District: 1	Congressional District: 1	TRS: 26N 5E 17

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? No
Statute: MTCA	NFA Date: 2/9/1999	Current VCP? No Past VCP? Yes
Site Rank: N/A	NFA Reason: Voluntary Cleanup Program Review	Brownfield? No
Site Manager: Lillie, John T	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Willina Ranch	Upland	No Further Action Required	NW	Lillie, John T	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified	R					

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
VCP Opinion on Cleanup Action	Completed	1/29/1999	2/9/1999
Site Status Changed to NFA	Completed		2/9/1999