

Cleanup Site Details

Cleanup Site ID: 3928

Cleanup Site ID: 3928 Facility/Site ID: 2870 UST ID: 4904 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: RG Haley International [Glossary](#)

Alternate Names: Haley RG Intl Corp, R G HALEY INTERNATIONAL CORP INC, RG Haley International, RG HALEY INTERNATIONAL CORP INC, RG HALEY INTL CORP

LOCATION

Address: CORNWALL AVE N City: BELLINGHAM Zip Code: 98227 County: Whatcom
 Latitude: 48.74231 Longitude: -122.49009 WRIA: 1 Legislative District: 40 Congressional District: 2 TRS: 38N 2E 36

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes
 Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
 Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No
 Site Manager: Schwarz, Julia Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
RG Haley International	Sediment	Cleanup Started	NW	McInerney, Lucy	Ecology-supervised or conducted
RG Haley International	Upland	Cleanup Started	NW	Adams, Mark	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics	C	C	C			
Dioxins/Furans	C	C	C	C		
Petroleum Products-Unspecified				C		
Polychlorinated biPhenyls (PCB)				C		
Polycyclic Aromatic Hydrocarbons	C	C	C			

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Hazardous Sites Listing/NPL	Completed		8/25/1992
Site Hazard Assessment/Federal Site Inspection	Completed		8/25/1992
Remedial Investigation and/or Feasibility Study	Completed	1/1/2000	2/1/2016
Order/Decree/Amendment	Completed	1/1/2004	2/12/2018
Remedial Investigation and/or Feasibility Study	Canceled	6/1/2004	4/30/2009

Cleanup Site Details

Cleanup Site ID: 3928

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Interim Action - Construction	Completed	1/1/2013	2/26/2014
Order/Decree/Amendment	Completed	1/1/2017	5/20/2024
Cleanup Action Plan	Completed	3/1/2017	4/20/2018
Cleanup Action - Engineering Design	In Process	4/16/2018	
Order/Decree/Amendment	In Process	8/17/2023	
Site Hazard Assessment/Federal Site Inspection	Completed		5/16/2024