

Cleanup Site Details

Cleanup Site ID: 3956

Cleanup Site ID: 3956 Facility/Site ID: 11293827 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Schwerin Concaves Walla Walla [Glossary](#)

Alternate Names: SCHWERIN CONCAVES, Schwerin Concaves Walla Walla

LOCATION

Address: 1106 SAPPOLIL RD City: WALLA WALLA Zip Code: 99362 County: Walla Walla
Latitude: 46.12191 Longitude: -118.23660 WRIA: 32 Legislative District: 16 Congressional District: 5 TRS: 7N 37E 6

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No
Site Manager: Treccani, Sandra Responsible Unit: Eastern Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Schwerin Concaves Walla Walla	Upland	Cleanup Started	EA	Treccani, Sandra	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater, Soil	Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance, Prevent the Reuse or Relocation of Site Soil, Ongoing Maintenance of Remedy, Prohibit Removal or Alteration of Existing Buildings	6/27/2023	2023-03574	Walla Walla	370831340008

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	C	C	S			

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		4/27/1989
Site Discovery/Release Report Received	Completed		10/15/1990
Early Notice Letter(s)	Completed		5/12/1999
Remedial Investigation and/or Feasibility Study	Completed	3/1/2000	6/30/2009
Site Hazard Assessment/Federal Site Inspection	Completed	6/14/2000	8/18/2000
Hazardous Sites Listing/NPL	Completed		8/29/2000
Interim Action	Completed	11/1/2002	3/31/2003
Interim Action - Construction	Completed	9/1/2020	11/1/2020

Cleanup Site Details

Cleanup Site ID: 3956

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Cleanup - Performance Monitoring	In Process	1/1/2021	