

Cleanup Site Details

Cleanup Site ID: 3956

Cleanup Site ID: 3956 **Facility/Site ID:** 11293827 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Schwerin Concaves Walla Walla [Glossary](#)
Alternate Names: SCHWERIN CONCAVES, Schwerin Concaves Walla Walla

LOCATION

Address: 1106 SAPPOLIL RD **City:** WALLA WALLA **Zip Code:** 99362 **County:** Walla Walla
Latitude: 46.12191 **Longitude:** -118.23660 **WRIA:** 32 **Legislative District:** 16 **Congressional District:** 5 **TRS:** 7N 37E 6

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 2 - Moderate-High Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Treccani, Sandra **Responsible Unit:** Eastern **Active Institutional Control?** Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Schwerin Concaves Walla Walla	Upland	Cleanup Started	EA	Treccani, Sandra	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater, Soil	Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance, Prevent the Reuse or Relocation of Site Soil, Ongoing Maintenance of Remedy, Prohibit Removal or Alteration of Existing Buildings	6/27/2023	2023-03574	Walla Walla	370831340008

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	C	C	S			

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		4/27/1989
Site Discovery/Release Report Received	Completed		10/15/1990
Early Notice Letter(s)	Completed		5/12/1999
Remedial Investigation and/or Feasibility Study	Completed	3/1/2000	6/30/2009
Site Hazard Assessment/Federal Site Inspection	Completed	6/14/2000	8/18/2000
Hazardous Sites Listing/NPL	Completed		8/29/2000
Interim Action	Completed	11/1/2002	3/31/2003
Interim Action - Construction	Completed	9/1/2020	11/1/2020

Cleanup Site Details

Cleanup Site ID: 3956

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Cleanup - Performance Monitoring	In Process	1/1/2021	