

Cleanup Site Details

Cleanup Site ID: 4007

Cleanup Site ID: 4007 Facility/Site ID: 4690075 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Car Crushing Hoko River Hwy 112 [Glossary](#)

Alternate Names: CAR CRUSHING HOKO RIVER HWY 112, VAN RIPER PROPERTY

LOCATION

Address: 11630 HWY 112 City: SEKIU Zip Code: 98381 County: Clallam
Latitude: 48.27500 Longitude: -124.36028 WRIA: 19 Legislative District: 24 Congressional District: 6 TRS: 32N 13W 15

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No
Site Manager: Southwest Region Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CAR CRUSHING HOKO RIVER HWY 112	Upland	Awaiting Cleanup	SW	Southwest Region	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	S	C	S			
Non-Halogenated Solvents	S	S	S			
Petroleum Products-Unspecified	C	C	S			

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Early Notice Letter(s)	Completed		5/20/2008
Initial Investigation / Federal Preliminary Assessment	Completed		5/20/2008
Site Discovery/Release Report Received	Completed		5/20/2008
Site Hazard Assessment/Federal Site Inspection	Completed	6/1/2009	2/2/2010
Hazardous Sites Listing/NPL	Completed		2/2/2010