

# Cleanup Site Details

Cleanup Site ID: 4099

Cleanup Site ID: 4099      Facility/Site ID: 8100630      UST ID: 620658      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Park Laundry Site      [Glossary](#)

Alternate Names: Park Laundry, PARK LAUNDRY SITE

## LOCATION

Address: 122 N MAIN AVE      City: RIDGEFIELD      Zip Code: 98642      County: Clark  
Latitude: 45.81605      Longitude: -122.74583      WRIA: 27      Legislative District: 18      Congressional District: 3      TRS: 4N 1W 38

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: 3 - Moderate Risk      NFA Reason: N/A      Brownfield? Yes  
Site Manager: Penner-Ash, Cam      Responsible Unit: Southwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Park Laundry Site	Upland	Cleanup Started	SW	Penner-Ash, Cam	Ecology-supervised or conducted
Hinrich's Property	Upland	Cleanup Started	SW	Penner-Ash, Cam	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	C	C				
Other Halogenated Organics	S	C				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Cleanup - Performance Monitoring	Canceled	1/1/2000	3/11/2019
Early Notice Letter(s)	Completed		4/27/2006
Initial Investigation / Federal Preliminary Assessment	Completed		4/27/2006
Site Hazard Assessment	Completed	7/6/2006	1/4/2007
Site Discovery/Release Report Received	Completed		10/9/2006
Initial Investigation / Federal Preliminary Assessment	Completed		10/9/2006
Early Notice Letter(s)	Completed		10/9/2006
Hazardous Sites Listing	Completed		1/4/2007

# Cleanup Site Details

Cleanup Site ID: 4099

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Site Hazard Assessment	Completed	1/14/2007	2/5/2007
Order/Decree/Amendment	Completed	7/29/2009	9/16/2020
Remedial Investigation and/or Feasibility Study	Completed	10/9/2009	9/4/2019
Cleanup Action Plan	Completed	5/1/2019	2/1/2023
Order/Decree/Amendment	In Process	1/1/2023	
SHARP Assessment	Completed		8/22/2024
Cleanup Action - Engineering Design	Completed	10/1/2024	11/26/2024
Cleanup - Construction	Completed	1/6/2025	4/18/2025
Cleanup - Performance Monitoring	In Process	4/18/2025	