

Cleanup Site Details

Cleanup Site ID: 4099

Cleanup Site ID: 4099 Facility/Site ID: 8100630 UST ID: 620658 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Park Laundry Site [Glossary](#)

Alternate Names: Park Laundry, PARK LAUNDRY SITE

LOCATION

Address: 122 N MAIN AVE City: RIDGEFIELD Zip Code: 98642 County: Clark
Latitude: 45.81605 Longitude: -122.74583 WRIA: 27 Legislative District: 18 Congressional District: 3 TRS: 4N 1W 38

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? Yes
Site Manager: Penner-Ash, Cam Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Park Laundry Site	Upland	Cleanup Started	SW	Penner-Ash, Cam	Ecology-supervised or conducted
Hinrich's Property	Upland	Cleanup Started	SW	Penner-Ash, Cam	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	C	C				
Other Halogenated Organics	S	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Cleanup - Performance Monitoring	Canceled	1/1/2000	3/11/2019
Early Notice Letter(s)	Completed		4/27/2006
Initial Investigation / Federal Preliminary Assessment	Completed		4/27/2006
Site Hazard Assessment	Completed	7/6/2006	1/4/2007
Site Discovery/Release Report Received	Completed		10/9/2006
Initial Investigation / Federal Preliminary Assessment	Completed		10/9/2006
Early Notice Letter(s)	Completed		10/9/2006
Hazardous Sites Listing	Completed		1/4/2007

Cleanup Site Details

Cleanup Site ID: 4099

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment	Completed	1/14/2007	2/5/2007
Order/Decree/Amendment	Completed	7/29/2009	9/16/2020
Remedial Investigation and/or Feasibility Study	Completed	10/9/2009	9/4/2019
Cleanup Action Plan	Completed	5/1/2019	2/1/2023
Order/Decree/Amendment	In Process	1/1/2023	
SHARP Assessment	Completed		8/22/2024
Cleanup Action - Engineering Design	Completed	10/1/2024	11/26/2024
Cleanup - Construction	Completed	1/6/2025	4/18/2025
Cleanup - Performance Monitoring	In Process	4/18/2025	