

Cleanup Site Details

Cleanup Site ID: 4099

Cleanup Site ID: 4099 **Facility/Site ID:** 8100630 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Park Laundry Site [Glossary](#)
Alternate Names: PARK LAUNDRY SITE

LOCATION

Address: 122 N MAIN AVE **City:** RIDGEFIELD **Zip Code:** 98642 **County:** Clark
Latitude: 45.81605 **Longitude:** -122.74583 **WRIA:** 27 **Legislative District:** 18 **Congressional District:** 3 **TRS:** 4N 1W 38

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 3 - Moderate Risk **NFA Reason:** N/A **Brownfield?** Yes
Site Manager: Penner-Ash, Cam **Responsible Unit:** Southwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Park Laundry Site	Upland	Cleanup Started	SW	Penner-Ash, Cam	Ecology-supervised or conducted
Hinrich's Property	Upland	Cleanup Started	SW	Penner-Ash, Cam	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	C	C				
Other Halogenated Organics	S	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Cleanup - Performance Monitoring	Canceled	1/1/2000	3/11/2019
Early Notice Letter(s)	Completed		4/27/2006
Initial Investigation / Federal Preliminary Assessment	Completed		4/27/2006
Site Hazard Assessment/Federal Site Inspection	Completed	7/6/2006	1/4/2007
Site Discovery/Release Report Received	Completed		10/9/2006
Initial Investigation / Federal Preliminary Assessment	Completed		10/9/2006
Early Notice Letter(s)	Completed		10/9/2006
Hazardous Sites Listing/NPL	Completed		1/4/2007

Cleanup Site Details

Cleanup Site ID: 4099

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	1/14/2007	2/5/2007
Order/Decree/Amendment	Completed	7/29/2009	9/16/2020
Remedial Investigation and/or Feasibility Study	Completed	10/9/2009	9/4/2019
Cleanup Action Plan	In Process	5/1/2019	