

Cleanup Site Details

Cleanup Site ID: 4121

Cleanup Site ID: 4121 **Facility/Site ID:** 1367331 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Stubblefield Salvage Yard [Glossary](#)
Alternate Names: Stubblefield Salvage Yard

LOCATION

Address: 595 OFFNER RD **City:** WALLA WALLA **Zip Code:** 99362 **County:** Walla Walla
Latitude: 46.06437 **Longitude:** -118.36800 **WRIA:** 32 **Legislative District:** 16 **Congressional District:** 5 **TRS:**

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Larimer, Katie **Responsible Unit:** Eastern **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Stubblefield Salvage Yard	Upland	Cleanup Started	EA	Larimer, Katie	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	C	S	S		S	
Conventional Contaminants, Organic	C	S	S		S	
Dioxins/Furans	S	S	S		S	
Halogenated Organics		S			S	
Metals - Other	S				S	
Metals Priority Pollutants	S				S	
Petroleum Products-Unspecified	C	S	S		S	
Polycyclic Aromatic Hydrocarbons	S	S	S		S	

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		10/19/2006
Site Discovery/Release Report Received	Completed		10/19/2006
Early Notice Letter(s)	Completed		1/31/2007

Cleanup Site Details

Cleanup Site ID: 4121

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	2/28/2007	8/3/2007
Hazardous Sites Listing/NPL	Completed		8/3/2007
Federal Emergency Response/Time-Critical Removal Action	Completed	10/1/2009	10/31/2009
Federal Emergency Response/Time-Critical Removal Action	Completed	4/1/2012	4/30/2012
Federal Non-Time Critical Removal Action	Completed	5/13/2013	6/28/2013
Remedial Investigation and/or FS Work Plan	Completed	9/17/2018	11/27/2018
Remedial Investigation and/or Feasibility Study	Completed	11/26/2018	11/30/2018