

Cleanup Site Details

Cleanup Site ID: 4146

Cleanup Site ID: 4146 **Facility/Site ID:** 21945598 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Duwamish Marine Center [Glossary](#)
Alternate Names: Duwamish Marine Center

LOCATION

Address: 6365 1ST AVE S **City:** SEATTLE **Zip Code:** 98108 **County:** King
Latitude: 47.54504 **Longitude:** -122.33581 **WRIA:** 9 **Legislative District:** 11 **Congressional District:** 7 **TRS:** 24N 4E 30

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Nale, Cliff **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Duwamish Marine Center	Upland	Cleanup Started	NW	Nale, Cliff	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics	C					
Metals - Other	C					
Metals Priority Pollutants	C					
Non-Halogenated Solvents	S	C				
Petroleum Products-Unspecified	C	C				
Polychlorinated biPhenyls (PCB)	C					
Polycyclic Aromatic Hydrocarbons	C	S				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		1/26/2001
Initial Investigation / Federal Preliminary Assessment	Completed		4/6/2001
VCP Opinion on Cleanup Action	Canceled	5/7/2002	
VCP Opinion on Site Cleanup	Completed	4/1/2005	6/1/2005

Cleanup Site Details

Cleanup Site ID: 4146

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Status Request	Completed	3/31/2006	6/16/2006
VCP Receipt of Plan or Report	Completed		4/28/2006
VCP Opinion on Cleanup Action	Completed	6/5/2006	7/3/2006
VCP Opinion on Cleanup Action Plan	Completed	9/20/2007	2/13/2008
VCP Opinion on Cleanup Action Plan	Completed	3/20/2008	4/7/2008
Site Hazard Assessment/Federal Site Inspection	Completed	6/15/2010	2/8/2012
Remedial Investigation and/or FS Work Plan	Completed	9/2/2011	1/15/2014
Order/Decree/Amendment	In Process	9/2/2011	
Hazardous Sites Listing/NPL	Completed		2/15/2012
Remedial Investigation and/or Feasibility Study	Completed	1/15/2014	9/30/2020
Remedial Investigation and/or Feasibility Study	In Process	10/1/2020	