

Cleanup Site Details

Cleanup Site ID: 4179

Cleanup Site ID: 4179 **Facility/Site ID:** 50534232 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Benenson Capital [Glossary](#)
Alternate Names: Benenson Bellevue II, Benenson Capital, Chevron 9 2581, Main Street Place Bellevue, Shop At First Street

LOCATION

Address: 110 108TH AVE NE **City:** BELLEVUE **Zip Code:** 98004 **County:** King
Latitude: 47.61118 **Longitude:** -122.19591 **WRIA:** 8 **Legislative District:** 41 **Congressional District:** 9 **TRS:** 25N 5E 32

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No
Site Manager: DeBoer, Chris **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Benenson Capital	Upland	Cleanup Started	NW	DeBoer, Chris	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	C	S				
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/5/1996
Initial Investigation / Federal Preliminary Assessment	Completed		7/25/1996
Early Notice Letter(s)	Completed		5/11/1998
VCP Opinion on Remedial Investigation	Completed	10/12/1999	3/9/2000
VCP Status Request	Completed	11/15/2006	3/15/2007