

Cleanup Site ID: 4179

Cleanup Site Details

Facility/Site ID: 50534232 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 4179

Cleanup Site Name: Benenson Capital Glossary

Alternate Names: Benenson Bellevue II, Benenson Capital, Chevron 9 2581, Main Street Place Bellevue, Shop At First Street

LOCATION

Address: 110 108TH AVE NE City: BELLEVUE Zip Code: 98004 County: King

Latitude: 47.61118 Longitude: -122.19591 WRIA: 8 Legislative District: 41 Congressional District: 9 TRS: 25N 5E 32

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: DeBoer, Chris Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Benenson Capital
 Upland
 Cleanup Started
 NW
 DeBoer, Chris
 Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	С	S				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/5/1996
Initial Investigation / Federal Preliminary Assessment	Completed		7/25/1996
Early Notice Letter(s)	Completed		5/11/1998
VCP Opinion on Remedial Investigation	Completed	10/12/1999	3/9/2000
VCP Status Request	Completed	11/15/2006	3/15/2007

Toxics Cleanup Program Report Generated: 5/21/2025 Page 1 of 1