

Cleanup Site Details

Cleanup Site ID: 42

Cleanup Site ID: 42 Facility/Site ID: 2906 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)
 Cleanup Site Name: Northwest Pipeline Bellingham [Glossary](#)
 Alternate Names: BELLINGHAM METER STATION 1, NORTHWEST PIPELINE BELLINGHAM, NORTHWEST PIPELINE/WILLIAM GAS PIPELINE

LOCATION

Address: BRITTON RD & MT BAKER HWY City: BELLINGHAM Zip Code: 98226 County: Whatcom
 Latitude: 48.79258 Longitude: -122.41450 WRIA: 1 Legislative District: 40 Congressional District: 1 TRS: 38N 3E 10

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
 Statute: MTCA NFA Date: 3/7/2013 Current VCP? No Past VCP? Yes
 Site Rank: 5 - Lowest Assessed Risk NFA Reason: Voluntary Cleanup Program Review Brownfield? No
 Site Manager: Myers, Dale R Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|-------------------------------|-----------|----------------------------|-----------|---------------|------------------------------------|
| NORTHWEST PIPELINE BELLINGHAM | Upland | No Further Action Required | NW | Myers, Dale R | Standard Voluntary Cleanup Program |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

| Contaminant | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
|----------------------------|------|-------------|---------------|----------|-----|---------|
| Arsenic | RB | | | | | |
| Metals Priority Pollutants | RB | | | | B | |

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|--|-----------|------------|---------------------------|
| Site Discovery/Release Report Received | Completed | | 10/21/1991 |
| Early Notice Letter(s) | Completed | | 12/31/1991 |
| Site Hazard Assessment/Federal Site Inspection | Completed | 3/24/2000 | 8/17/2000 |
| Hazardous Sites Listing/NPL | Completed | | 8/29/2000 |
| VCP Opinion on Interim Action | Completed | 3/20/2007 | |
| VCP Opinion on Cleanup Action | Completed | | 7/12/2007 |
| VCP Receipt of Plan or Report | Completed | | 12/1/2012 |
| VCP Receipt of Plan or Report | Completed | | 1/14/2013 |

Cleanup Site Details

Cleanup Site ID: 42

| SITE ACTIVITIES | | | |
|---------------------------------------|---------------|-------------------|--------------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| VCP Opinion on Site Cleanup | Completed | 1/14/2013 | 3/7/2013 |
| Site Status Changed to NFA | Completed | | 3/7/2013 |
| Remove site from Hazardous Sites List | Completed | | 3/30/2015 |