

Cleanup Site Details

Cleanup Site ID: 4228

Cleanup Site ID: 4228 Facility/Site ID: 94656838 UST ID: 328 [Site Page](#) [Site Documents](#) [View Map](#)
 Cleanup Site Name: Solid Wood Inc [Glossary](#)
 Alternate Names: SOLID WOOD INC

LOCATION

Address: 700 W BAY DR NW City: OLYMPIA Zip Code: 98502 County: Thurston
 Latitude: 47.05141 Longitude: -122.91257 WRIA: 13 Legislative District: 22 Congressional District: 10 TRS: 18N 2W 37

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes
 Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
 Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No
 Site Manager: Teel, Steve Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
SOLID WOOD INC	Upland	Awaiting Cleanup	SW	Teel, Steve	Ecology-supervised or conducted
SOLID WOOD INC	Sediment	No Further Action Required	SW	Teel, Steve	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Dioxins/Furans	B			S		
Metals Priority Pollutants	B	B		S		
Petroleum Products-Unspecified	C	C		B		
Polycyclic Aromatic Hydrocarbons	C	B		S		

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Remedial Investigation and/or Feasibility Study	In Process	11/29/2007	
Site Hazard Assessment/Federal Site Inspection	Completed	5/12/2008	6/11/2008
Hazardous Sites Listing/NPL	Completed		6/11/2008
Interim Action	Completed	7/27/2009	11/18/2010
Remedial Investigation and/or FS Work Plan	Completed	10/2/2013	11/6/2013

Cleanup Site Details

Cleanup Site ID: 4228

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Remedial Investigation and/or FS Work Plan	Completed	6/1/2014	5/13/2015