

Cleanup Site Details

Cleanup Site ID: 4257

Cleanup Site ID: 4257 Facility/Site ID: 12832256 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Smith Kem Ellensburg Inc

[Glossary](#)

Alternate Names: SMITH KEM ELLENSBURG INC

LOCATION

Address: 200 S RAILROAD AVE **City:** ELLENSBURG **Zip Code:** 98926 **County:** Kittitas
Latitude: 46.99113 **Longitude:** -120.55463 **WRIA:** 39 **Legislative District:** 13 **Congressional District:** 8 **TRS:** 17N 18E 2

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes
Site Rank: 3 - Moderate Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Mefford, John **Responsible Unit:** Central **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Smith Kem Ellensburg Inc	Upland	Cleanup Started	CE	Mefford, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic		C				
Halogenated Pesticides	C	C				
Metals Priority Pollutants	S	S				
Non-Halogenated Pesticides	B	B				
Petroleum-Diesel	C	C				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		3/17/2008
Early Notice Letter(s)	Completed		6/2/2008
Site Hazard Assessment/Federal Site Inspection	Completed	6/30/2008	8/14/2008
Hazardous Sites Listing/NPL	Completed		8/14/2008
Non-LUST Ind Report Received	Completed		8/9/2013
Non-LUST Ind Report Received	Completed		10/8/2014

Cleanup Site Details

Cleanup Site ID: 4257

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Non-LUST Ind Report Received	Completed		10/23/2014
Non-LUST Ind Report Received	Completed		3/9/2015
Non-LUST Ind Report Received	Completed		7/10/2015
Order/Decree/Amendment	Completed	9/25/2015	4/7/2023
Remedial Investigation and/or FS Work Plan	Completed	2/29/2016	8/1/2016
Non-LUST Ind Report Received	Completed		6/1/2016
Remedial Investigation and/or Feasibility Study	Completed	8/1/2016	1/21/2022
Order/Decree/Amendment	In Process	4/12/2022	
Cleanup Action Plan	Completed	5/26/2022	5/3/2023
Cleanup Action - Engineering Design	In Process	5/3/2023	