

Cleanup Site Details

Cleanup Site ID: 4298

Cleanup Site ID: 4298 Facility/Site ID: 2744 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Everett Smelter [Glossary](#)

Alternate Names: ASARCO EVERETT, EVERETT SMELTER, EVERETT SMELTER SLAG SITE, PUGET SOUND REDUCTION CO

LOCATION

Address: SR 529 & E MARINE VIEW DR City: EVERETT Zip Code: 98201 County: Snohomish
Latitude: 48.00989 Longitude: -122.19228 WRIA: 7 Legislative District: 38 Congressional District: 2 TRS: 29N 5E 8

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No
Site Manager: Matthews, Sandra Responsible Unit: Northwest Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Everett Smelter	Upland	Cleanup Started	NW	Matthews, Sandra	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater, Soil	Require Educational Programs, Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance, Ongoing Maintenance of Remedy, Prohibit Removal or Alteration of Existing Buildings	4/5/2005	200504050143; 200504050142; 200504050141; 200504050140; 200504050135;	Snohomish	Multiple (see comments)

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	C	C	C		B	
Petroleum Products-Unspecified	B					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		12/1/1990
Initial Investigation / Federal Preliminary Assessment	Completed		12/13/1990
Site Hazard Assessment/Federal Site Inspection	Completed	2/1/1991	7/30/1991
Early Notice Letter(s)	Completed		3/13/1991
Hazardous Sites Listing/NPL	Completed		8/30/1991
Interim Action	Completed	8/1/1992	1/31/1993
Remedial Investigation and/or Feasibility Study	Completed	8/1/1992	6/30/1999

Cleanup Site Details

Cleanup Site ID: 4298

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Interim Action	Completed	2/1/1997	12/31/2005
Order/Decree/Amendment	In Process	3/14/1997	
Cleanup Action Plan	Completed	6/1/1998	11/19/1999
Cleanup - Construction	In Process	11/19/1999	
Cleanup Action - Engineering Design	Completed	11/19/1999	12/30/2001