

# Cleanup Site Details

Cleanup Site ID: 4306

Cleanup Site ID: 4306      Facility/Site ID: 6773108      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Evergreen Fuels      [Glossary](#)

Alternate Names: CC COLE & SONS, EVERGREEN FUELS

## LOCATION

Address: 661 E PINE ST      City: SHELTON      Zip Code: 98584      County: Mason  
Latitude: 47.21423      Longitude: -123.08830      WRIA: 14      Legislative District: 35      Congressional District: 10      TRS: 20N 3W 20

## DETAIL

Status: Construction Complete-Performance Monitoring      NFA Received? No      Is PSI site? Yes  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: N/A      NFA Reason: N/A      Brownfield? No  
Site Manager: Smith, Sandy      Responsible Unit: Southwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
EVERGREEN FUELS	Sediment	No Further Action Required	SW	Mercuri, Joyce	Ecology-supervised or conducted
EVERGREEN FUELS	Upland	Construction Complete-Performance Monitoring	SW	Smith, Sandy	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic				B		
Base/Neutral/Acid Organics				B		
Benzene	C	RB	RB			
Bioassay Benthic Failures				B		
Metals - Other				B		
Metals Priority Pollutants				B		
Organotins				B		
Other Non-Halogenated Organics	RB	B	RB			
Petroleum Products-Unspecified	B		B	B		
Petroleum-Diesel	C	C	RB			
Petroleum-Gasoline	C	RB	RB			
Petroleum-Other		C				
Polycyclic Aromatic Hydrocarbons	B	B	B			

# Cleanup Site Details

Cleanup Site ID: 4306

**Key:**

B - Below Cleanup Level  
S - Suspected

C - Confirmed Above Cleanup Level  
R - Remediated

RA - Remediated-Above  
RB - Remediated-Below

**SITE ACTIVITIES**

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		4/30/2003
Early Notice Letter(s)	Completed		5/8/2003
Remedial Investigation and/or Feasibility Study	Completed	1/30/2004	7/15/2006
Order/Decree/Amendment	Completed	4/2/2004	11/29/2006
Cleanup Action Plan	Completed	6/15/2006	10/30/2006
Order/Decree/Amendment	In Process	7/1/2006	
Interim Action	Completed	9/21/2006	10/5/2006
Cleanup Action - Engineering Design	Completed	10/30/2006	7/30/2007
O & M	In Process	2/15/2007	
Cleanup - Construction	Completed	2/15/2007	7/31/2007
Cleanup - Performance Monitoring	In Process	4/5/2007	
Monitoring	Completed	6/21/2021	1/31/2022