

Cleanup Site ID: 4341

Cleanup Site Details

Facility/Site ID: 29985184 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 4341

Cleanup Site Name: Eds Transmission Exchange

Alternate Names: Eds Transmission Exchange

LOCATION

Address: 10226 HWY 99 City: MARYSVILLE Zip Code: 98270 County: Snohomish

Latitude: 48.03762 Longitude: -122.15305 WRIA: 7 Legislative District: 38 Congressional District: 2 TRS: 30N 5E 34

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 7/24/2015 Current VCP? No Past VCP? Yes

Site Rank: 3 - Moderate Risk NFA Reason: Voluntary Cleanup Program Review Brownfield? No

Site Manager: Nye, Roger Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 EDS TRANSMISSION
 Upland
 No Further Action Required
 NW
 Nye, Roger
 Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Halogenated Organics			S		S		
Metals Priority Pollutants	RB	RB	S		S		
Petroleum Products-Unspecified			S		S		
Petroleum-Other	RB	RB					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment	Completed	8/13/1999	1/28/2000
Hazardous Sites Listing	Completed		2/29/2000
VCP Receipt of Plan or Report	Completed		5/9/2014
VCP Opinion on Site Cleanup	Completed	5/15/2014	7/24/2015
Site Status Changed to NFA	Completed		7/24/2015
Remove site from Hazardous Sites List	Completed		7/24/2015

Toxics Cleanup Program Report Generated: 10/27/2025 Page 1 of 1