

Cleanup Site Details

Cleanup Site ID: 4358

Cleanup Site ID: 4358 **Facility/Site ID:** 457 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Terrace Heights Landfill Pesticide Dump [Glossary](#)
Alternate Names: Terrace Heights Landfill Pesticide Dump, TERRACE HTS LANDFILL PESTICIDE

LOCATION

Address: 7601 ROZA HILL DR **City:** YAKIMA **Zip Code:** 98901 **County:** Yakima
Latitude: 46.60886 **Longitude:** -120.39222 **WRIA:** 37 **Legislative District:** 15 **Congressional District:** 4 **TRS:** 13N 19E 13

DETAIL

Status: No Further Action **NFA Received?** Yes **Is PSI site?** No
Statute: MTCA **NFA Date:** 1/31/2024 **Current VCP?** No **Past VCP?** No
Site Rank: 4 - Low-Moderate Risk **NFA Reason:** Independent Cleanup Reviewed by Ecology **Brownfield?** No
Site Manager: Central Region **Responsible Unit:** Central **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Terrace Heights Landfill Pesticide Dump	Upland	No Further Action Required	CE	Central Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Pesticides-Unspecified	RB					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		1/19/1994
Non-LUST Ind Report Received	Completed		1/13/1995
Hazardous Sites Listing/NPL	Completed		2/21/1995
Site Hazard Assessment/Federal Site Inspection	Completed		2/21/1995
Remove site from Hazardous Sites List	Completed		1/31/2024
Site Status Changed to NFA	Completed		1/31/2024